

SERVICE REPORT

Vessel	ROYAL LADY		
IMO No	9300829	Report No	20250306-1
Flag	ANTIGUA BARBUDA	Service Date	06.MARCH.2025
Call Sign/MMSI	V2YA3	Port	SKAGEN, DENMARK

Equipment to be Serviced	Brand/Model	Reason of Attendance

Description of Work Performed (Equipment – Cause – Actions Taken for Solution)

DNV ANNUAL RADIOSURVEY , FURUNO VR5000 VDR APT & RE-PROGRAMMING

ATTENDED VESSEL FOR VDR ANNUAL PERFORMANCE TEST AND GMDSS RADIO SURVEY. CARRIED OUT VDR APT AS PER MANUFACTURER APT PROCEDURE AND VDR FOUND FULLY OPERATIONAL WITH ALL FUNCTIONS. DOWNLOADED LAST 12 HOURS RECORDS, WE WILL BE SENDE TO MANUFACTURER FOR ANALYSE COC WILL BE PROVIDED BY MANUFACTURER AFTER ANALYSING AND APPROVOMENT OF RECEIVED DATA.

CARRIED OUT GMDSS RADIO INSPECTION AND FOUND THAT ALL GMDSS EQUIPMENT FULLY OPERATIONAL WITH ALL FUNCTIONS. TESTED ALL. FOUIPMENT, CHECKED BATTERIES. HRU ETC. AND CONFIRMED ALL OF THEM STILL VALID. FILLED UP RADIO CHECKLIST, CERTIFICATES, VDR TEST REPORTS AND HANDED OVER TO THE MASTER.

ANNUAL SURVEYS COMPLETED WITHOUT ANY REMARK.

ALSO RE-PROGRAMMING OF THE NAVIGATION EQUIPMENTS HAS BEEN COMPLETED SUCCESSFULLY.

Units/Spares Delivered					
Qty	Units/Spares	Serial Number	Qty	Units/Spares	Serial Number

Service Engineer	Date	Start	End	Total Time	Description
					Travel
					Wait
					Labor/Delivery
					Travel

Service Engineer (Name - Signature - Stamp)	Vessel Representative (Name - Signature - Stamp)
	 